


4-Way Pipe Clothing Rack



List of Parts



Assembly

1. Screw pipe (C) and pipe (C1) together.
2. Screw base (B) pipes into pipe (D).
3. Screw vertical pole (C & C1) into base (B & D). Flip rack upside down. With two people, grab base (B) pipes and rotate clockwise until base (B & D) are as tight as possible with flange feet or wheels facing opposite direction of vertical pole (See figure 1).
4. Flip rack right side up. Adjust vertical pole (C & C1) if needed so it is straight up and down.
5. Screw (A) pipes into vertical pole (C & C1).

**** Never Overload Rack; Keep Items Evenly Distributed on Rack****

Figure 1

